

Date: Friday, 09/05/2008 1:45:20 PM
User: Julie Lecocq

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : STOP
Job Number : 39152A
Estimate Number : 10731
P.O. Number : Part Number : D23243
This Issue : 09/05/2008 S.O. No. : Drawing Number : D2324 REV. C
Prsht Rev. : NC Project Number : N/A
First Issue : / / Type : SMALL /MED FAB Drawing Revision : C
Previous Run : 36749A Material :
Written By : Due Date : 05/06/2008 Qty: 20 Um: Each
Checked & Approved By : JUL 08.05.09
Comment : Est: E 03.02.28 Reformat; Incorporated D2324-3 & D2324-5 K
J/RF

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description :

1.0 M6061T6B0750X00750 6061-T6 Bar .75" x .75"



Comment: Qty.: 0.5565 f(s)/Unit Total: 11.1300 f(s)
6061-T6 Bar 0.75" x 0.75"

M107387

Material: 6061-T6/6511 (QQ-A-200/8) or (QQ-A-225/8) or 5052-H34 (QQ-A-225/7) or (QQ-A-250/8)
(M6061T6B0.750x00.750) Batch: M102476 x 10 pcs J.F.

2.0 BAND SAW BAND SAW



Comment: BAND SAW

Cut blanks: (0.75" x 0.75") x 5.75" Long Bar

J.F. /

3.0 HAAS1 HAAS CNC VERTICAL MACHINING #1



Comment: HAAS CNC VERTICAL MACHINING #1
1- Machine as per Folio D2324-3 and Dwg D2324
2- Deburr and Tumble to remove sharp edges
Identify as D2324-3

J.F. / mmf 08/05/20

4.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

J.F. / mmf 08/05/20

5.0 QC8 SECOND CHECK



Comment: SECOND CHECK

mmf 08/05/20

(20)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Friday, 09/05/2008 1:45:21 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STOP

Job Number: 39152A

Part Number: D23243

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

RD/BJ 08-05-20

(20)

7.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT ALODINE

JS 08/05/21 (20)

8.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: *ST26*

JS 08/05/21 (20)

9.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/05/22

Job Completion



MF 08-05-21

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries

DART


DESIGN	DRAWN BY	DART AEROSPACE LTD	
B WILLIAMS	PH	VICTORIA INTERNATIONAL AIRPORT, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO.	REV. C
		D2324	SHEET 1 OF 1
DATE		TITLE	SCALE
04.12.14		STRUT	
A	94.11.08	NEW ISSUE	
B	96.05.07	UPDATE MATERIALS	
C	04.12.14	UPDATE NOTES	

RELEASED04.12.16 *[Signature]***D2324 STRUT ASSEMBLY**

1) IDENTIFY WITH DART P/N D2324 USING FINE POINT PERMANENT INK MARKER

**D2324-3**

- 1) MATERIAL: 6061-T6/T651 BAR (QQ-A-200/8) 0.75 X 0.75
(REF DART SPEC. M6061T6B0.750X0.750)
- 2) FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4.1
POWDERCOAT WHITE (4.3.5.1) PER DART QSI 005 4.3
- 3) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) ALL TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

**D2324-5**

- 1) MATERIAL: AISI 304/316 STAINLESS STEEL SHEET 16 GAUGE (0.063 THICK)
(REF DART SPEC. M304S16GA)
- 2) FINISH: POWDERCOAT WHITE (4.3.5.1) PER DART QSI 005 4.3
- 3) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) ALL TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 3915217

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries